National Transportation Safety Board
FOREIGN NOTIFICATION
AVIATION

NTSB ID: DCA12RA148 Most Critical Injury: None

Occurrence Date: 09/11/2012 Investigated By: Foreign

Location/Time

 Nearest City/Place
 State
 Zip Code
 Local Time
 Time Zone

 Shanghai
 0309
 UTC

Occurrence Type: Incident

Aircraft Information

Registration Number | Aircraft Manufacturer | Model/Series Number

VQ-BLR BOEING 747-8F

Type of Aircraft: Airplane Amateur Built Aircraft?

Injury Summary: Fatal Serious Minor None 2

Revenue Sightseeing Flight: Air Medical Transport Flight:

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

*** Note: The foreign authority was the source of this information. ***

On September 11, 2012 at about 1109 China Standard Time (0309 UTC), a Boeing 747-8F, registration VQ-BLR, equipped with GEnx-2B engines and operated by Air Bridge Cargo Airlines, experienced an engine failure and subsequently rejected takeoff at Shanghai Pudong International Airport, Shanghai, China. The aircraft was being operated as a cargo flight and there were no injuries to the two crewmembers on board.

The incident is being investigated by the Civil Aviation Administration of China (CAAC). The NTSB has designated a U.S. Accredited Representative under the provisions of ICAO Annex 13 as the state of manufacture for the aircraft and engines.

Inquiries regarding this incident should be directed to:

Office of Aviation Safety Civil Aviation Administration of China 155 Dongsi Street West Beijing 100710 China Updated on Sep 19 2012 7:27PM